

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
1	BRS	L2	374	301/36.1	USPAT; EPO; JPO; DERWENT	2004/01/28 10:02		
2	BRS	L4	283	"wheel assembly" same bushing	USPAT; EPO; JPO; DERWENT	2004/01/28 10:06		
3	BRS	L5	3	"wheel assembly" same bushing same (independent or independently) same (rotation or rotating)	USPAT; EPO; JPO; DERWENT	2004/01/28 10:06		
4	BRS	L6	622	"wheel assembly" same (bushing or spacer)	USPAT; EPO; JPO; DERWENT	2004/01/28 10:09		
5	BRS	L7	5	"wheel assembly" same (bushing or spacer) same (independent or independently) same (rotation or rotating)	USPAT; EPO; JPO; DERWENT	2004/01/28 10:06		
6	BRS	L8	18	"wheel assembly" same (bushing or spacer) same (first or second) same hub	USPAT; EPO; JPO; DERWENT	2004/01/28 10:10		
7	BRS	L1	102	301/36.2	USPAT; EPO; JPO; DERWENT	2004/01/28 10:24		
8	BRS	L3	60	301/36.3	USPAT; EPO; JPO; DERWENT	2004/01/28 10:45		
9	BRS	L11	189	384/271	USPAT; EPO; JPO; DERWENT	2004/01/28 10:51		
10	BRS	L10	319	384/275	USPAT; EPO; JPO; DERWENT	2004/01/28 10:56		